CORRES. CONTROL OUTGOING LTR NO

DOE ORDER # 4760 : 1 RF 65476

DIST AMARAL, M.E. BERMAN, H.S. BRANCH DB CARNIVAL, G.J. COPP, R.D.

DAVIS, J.G. FERRERA, D.W. HANNI, B.J. HARMAN, LK. HEALY, T.J.

HEDAHL T. HILBIG, J.G.

KELL A.E.

KIRBY, W.A KUESTER, A.W MAHAFFEY, J.W.

MANN, H.P

MARX, G.E. McDCNALD, M.M.

MCKENNA, F.G. MONTROSE, J.K.

MORGAN, R.V.

POTTER, G.L.

PIZUTTO, G.L. AISING, T.L.

SANDLIN, N.B. SETLOCK, G.H.

STEWART, D.L.

SWANSON, E.R.

WILKINSON, R.B.

FEKTINGH RI

CORRES CONTROL

ADMIN RECORD/080

HFHCHURN

PATS/T130G CLASSIFICATION:

TRAFFIC

UCNI UNCLASSIFIED CONFIDENTIAL SECRET

Berman, S Anderson G Fuller, N.A

STIGER, S.G. SULLIVAN, M.T

WILSON, J.M.

WYANT, R.D. Cowdery Busoy, W. S.


HUTCHINS, N. M.

EGRG ROCKY FLATS

FG&G ROCKY FLATS, INC.

EX ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 (303) 966-7000

May 27, 1994



000031414

94-RF-05976

S. Slaten Project Manager **Environmental Restoration** DOE/RFFO

SAMPLING FOR POLYCHLORINATED BIPHENYLS (PCBs) IN INDIVIDUAL HAZARDOUS SUBSTANCE SITE 116.1 - SBS-004-94

Individual Hazardous Substance Site 116.1 has been determined to be located in an area where there is possible PCB contamination from a previous transformer leak. The transformer was located on the roof of Building 447 and appears to have a berm around it. The transformer is believed to have leaked prior to its removal in 1987. This area is located above the loading dock in Individual Hazardous Substance Site 116.1.

The approved Operable Unit (OU)12 RCRA [Resource Conservation & Recovery Act] Facility Investigation/Remedial Investigation (RFI/RI) currently does not include PCBs as an analyte in Individual Hazardous Substance Site 116.1. Adding PCBs as an analyte would cost \$150 per sample and should not exceed a total of \$1,650. It is the position of EG&G Rocky Flats, Inc. and Remediation Project Management that adding PCBs to the analyte list for those samples in the area of concern would be prudent.

Your concurrence to add PCBs to these samples is requested. Please sign the concurrence line below and return a copy to me.

Attached please find a map from the preliminary PCB investigation known as Site No. 9, a picture of Site No. 9, and a map of the sampling in Individual Hazardous Substance Site 116.1 from the approved OU 12 Work Plan.

If there are any questions regarding this transmittal, please feel free to contact me at extension 8670.

Date

CONCURRENCE:

AUTHORIZED CLASSIFIED N DOCUMENTAL HOLDER REVIEW WAIVER PER CLASSIFICATION OFFICE

IN REPLY TO RFP CC NO:

ACTION ITEM STATUS

ARTIAL

AF-16469 (Rev. 11/93)

OPEN

SBS:alk LTR APPROVALS:

CLOSED

X

×

X

XX

ORIG & TYPIST INITIALS

Orig. and 1 cc - S. Slaten

Project Manager - Operable Unit 12

Remediation Project Management

Attachment: As stated


S. Slaten


S. B. Smith

Project Manager

ADMIN RECCRD







3/4

